

## System Sensor Europe Lead Times for Week Commencing 19<sup>th</sup> July 2021

July 2021

Due to increased demand and a temporary component shortage, we are currently experiencing production delays and longer lead times. We appreciate your patience and we assure you that we are doing everything we can to serve you as quickly as possible.

Product Family	Lead Time in Working Days
Intelligent Wired Detectors	13
Conventional Wired Detectors	10
Intelligent Modules	15
Intelligent Wireless Detectors	13